

FINAL YEAR PROJECT REPORT

Sewing room losses



Project Advisor

SIR UMAIR MUKHTAR

Submitted By

M. AMEEN SHABBIR	081120-087
ZAFAR LEGHARI	081120-105

Department of Textile Engineering

University of Management and Technology

Acknowledgements

First of all, we would like to thank Al-Mighty **ALLAH** for giving us strength to complete our final year project. We truly acknowledge the cooperation and help by **SIR UMAIR MUKHTAR**, Project Advisor, University of Management and Technology. He has been a constant source of guidance throughout the course of this project. We are also thankful to our friends and families whose silent support led us to complete our project.

M. AMEEN SHABBIR

081120-087

ZAFAR LEGHARI

081120-105

Contents

Contents.....	3
1 INTRODUCTION OF TEXTILES AND APPAREL INDUSTRY.....	Error! Bookmark not defined.
2 LITERATURE REVIEW AND METHODOLOGY	Error! Bookmark not defined.
2.1 Literature review	Error! Bookmark not defined.
2.2 Methodology.....	Error! Bookmark not defined.
3 ABOUT PROJECT	Error! Bookmark not defined.
3.1 Topic.....	Error! Bookmark not defined.
3.2 Project Description.....	Error! Bookmark not defined.
3.2.1 Introduction.....	Error! Bookmark not defined.
3.2.2 Our Approach	Error! Bookmark not defined.
4 TIME LOSSES DUR TO REWORK.....	Error! Bookmark not defined.
4.1 Activities	Error! Bookmark not defined.
4.1.1 Activity No: 1	Error! Bookmark not defined.
4.1.2 Activity No: 2	Error! Bookmark not defined.
4.1.3 Activity No: 3	Error! Bookmark not defined.
4.1.4 Activity No: 4	Error! Bookmark not defined.
4.1.5 Activity No: 5	Error! Bookmark not defined.
4.1.6 Activity No: 6	Error! Bookmark not defined.
4.1.7 Activity No: 7	Error! Bookmark not defined.
4.2 Reasons of rework.....	Error! Bookmark not defined.
4.2.1 Operator skills	Error! Bookmark not defined.
4.2.2 New operations involved	Error! Bookmark not defined.
4.2.3 Conclusion	Error! Bookmark not defined.
4.2.4 Problems due to rework.....	Error! Bookmark not defined.
4.2.5 Proposals	Error! Bookmark not defined.
4.2.6 Solution	Error! Bookmark not defined.

4.2.7	Tips to reduce rework	Error! Bookmark not defined.
5	Miscellaneous calculations.....	Error! Bookmark not defined.
5.1	Activities	Error! Bookmark not defined.
5.1.1	Activity: 1.....	Error! Bookmark not defined.
5.1.2	Activity: 2.....	Error! Bookmark not defined.
5.1.3	Activity: 1.....	Error! Bookmark not defined.
5.1.4	Activity: 2.....	Error! Bookmark not defined.
5.2	Conclusion	Error! Bookmark not defined.
5.3	Proposal for preventive maintenance.....	Error! Bookmark not defined.
5.3.1	Lubricating system.....	Error! Bookmark not defined.
5.3.2	Mechanical portion	Error! Bookmark not defined.
5.3.3	Pneumatic portion.....	Error! Bookmark not defined.
5.3.4	Electrical portion	Error! Bookmark not defined.
5.3.5	Electronics portion	Error! Bookmark not defined.
6	Sewing Thread.....	Error! Bookmark not defined.
6.1	Sewing Thread	Error! Bookmark not defined.
6.1.1	Types of Thread	Error! Bookmark not defined.
6.2	Thread wastage and degradation due to poor storage	Error! Bookmark not defined.
6.2.1	Causes of degradation.....	Error! Bookmark not defined.
6.3	Proposed factor to be considered during the storage	Error! Bookmark not defined.
6.3.1	Cleanliness.....	Error! Bookmark not defined.
6.3.2	Light.....	Error! Bookmark not defined.
6.3.3	Temperature and humidity	Error! Bookmark not defined.
6.4	Choosing the Right Thread	Error! Bookmark not defined.
6.5	Thread cost.....	Error! Bookmark not defined.
6.6	Determining thread demands	Error! Bookmark not defined.
6.7	Factor of influence on the thread demand	Error! Bookmark not defined.
6.7.1	The influence of stitch density	Error! Bookmark not defined.
6.7.2	The influence of fabric weight.....	Error! Bookmark not defined.
6.7.3	The influence of tension on stitches	Error! Bookmark not defined.
6.8	Conclusion	Error! Bookmark not defined.
6.9	Future Work	Error! Bookmark not defined.

7 References..... **Error! Bookmark not defined.**

Abstract

The aim of this project is to develop a strategy through which defects happen in the chain of manufacturing garments and ready garments can be minimized. As our country, Pakistan is an under-developed country so this was need of time to minimize the defects to avoid the rejection.

In this project we have done work on the minimization of defects and purposed a better strategy to avoid defects, to produce more flexibility in styles, to increase the production, to complete the order on time and with minimum number of defects for the sake of rejection. As the other countries like Bangladesh, china and india are also a good garment producer and they are also producing in cheaper rates then Pakistan. So this is required to improve in our quality and more style to defeat the competitors.

We have discussed approx. every defect that can happen in the sewing section and purposed the way to minimize it. Also we have purposed some two to three extra operator for the sake of time loss in production line. Also suggested that the person working on production line should know some basic skill regarding.

Maintenance of machine is also a big issue. Sometimes the defects like miss stitch also happens due to machine problems and for this reason it is suggested that every operator should clean its machine when start working or leaving the machine.